INSPECTION REPORT

Partial Complete XXX Exploration Inspection Date: 08/27/2003 Time: 10:00AM-2:30PM Date of Last Inspection: 07/15/2003

Mine Name: Horizon Mine	County: Carbon	Permit Number: <u>C/007/020</u>				
Permittee and/or Operator's Name: Hidden Splendor Resources, Inc.						
Business Address: 50 West Liberty Street, Suite 880, Reno, Nevada 89501						
Company Official(s): Shane Hansen						
State Official(s): Stephen J. Demczak Federal Official(s): None						
Weather Conditions: Cloudy, 70's						
Type of Mining Activity: Underground XXX Surface Prep Plant Other						
Existing Acreage: Permitted 711 Disturbed 9 Regraded Seeded Seeded						
Status: Active						

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	$\overline{[X]}$		<u>[X]</u>	口
3.	TOPSOIL	<u>[X]</u>	ΞĪ	<u>[X]</u>	
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box	[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	لَــاً	[X]	Ĺĺ
c.	OTHER SEDIMENT CONTROL MEASURES	[X]	Ш	Ĺĺ	
d.	WATER MONITORING	[X]		[X]	
e.	EFFLUENT LIMITATIONS	[X]			
5.	EXPLOSIVES	[X]			
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]			
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[X]		
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]			
10.	SLIDES AND OTHER DAMAGE	[X]			
11.	CONTEMPORANEOUS RECLAMATION	[X]	\Box		
12.	BACKFILLING AND GRADING	[X]			
13.	REVEGETATION	[X]			
14.	SUBSIDENCE CONTROL	[X]	\Box		
15.	CESSATION OF OPERATIONS	[X]		[X]	
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]			
b.	DRAINAGE CONTROLS	[X]			
17.	OTHER TRANSPORTATION FACILITIES	[X]			
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]		[X]	
19.	AVS CHECK (4 th Quarter- April, May, June)	[X]			
20.	AIR QUALITY PERMIT	[X]			
21.	BONDING & INSURANCE	[X]		[X]	\Box

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/020</u> DATE OF INSPECTION: <u>08/27/2003</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The Horizon Mining Permit has been transferred to Hidden Splendor Resources, Inc as of July 1, 2003. The permit will expire on October 11, 2006. There are two conditions set forth in the Mining and Reclamation Permit. These are a) Hidden Splendor Resources, Inc will submit water quality data by using the Electronic Data Input System, and b) to update the permit transfer information in the Mining and Reclamation Plan by August 1, 2003. The permittee requested an extension until September 15, 2003 and it was granted.

No permitting actions have been submitted to the Division by the new permittee. However, the permittee is in the process of updating the transfer information in the Mining and Reclamation Plan.

The SPPC Plan was last reviewed in September 2003.

2. SIGNS AND MARKERS

New identification information has been installed as it pertains to Hidden Splendor Resources.

3. TOPSOIL

The permittee was in the process of installing the straw bales around the topsoil pile.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked. A water hose was partially in a diversion. The permittee removed the water hose.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was not discharging during the inspection. No discharge from the pond has occurred for the quarter.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Water monitoring has been taken for the second quarter and will be entered into the Electronic Data System by the end of the third quarter.

8. NONCOAL WASTE

The property was clear of non-coal waste material.

INSPECTION REPORT

(Continuation Sheet)

PERMI	T NUMBER: <u>C/007/020</u>		DATE OF INSPECTION: <u>08/27/2003</u>
15.	CESSATION OF OPERAT		
18.	SUPPORT FACILITIES/U	TILITY INSTALLATIONS	
	The permittee is nearly finish	ned with the redesigned beltline.	
21.	BONDING AND INSURA	NCE	
		y will expire on July 1, 2004. T	the minimum requirements of the he company supplying the insurance is
Inspect	tor's Signature: Stephen J. D	Demczak #39	Date: September 3, 2003

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Alexander Walker, Hidden Splendor, SLC, via email
Price Field office
O:\007020.HZN\Compliance\2003\c_0827.doc